

BLDG NO
A-1

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
NB4-04366-22	11/7/63	E 1764	Renovation
7-386d	1-17-74	285	Paint (1) Class Rm
70-4309	5-8-70	1137	Replace (2) overhead steam ^{unit} with heater
1-3400	9-18-70	1864	Remove & re-install cap flashing
71-1150	3-7-72	1042	Construct a concrete pad
72-5228	5-19-72	0/E	barricade along sewage drain
3-4606	3-2-73	0/E	Repair sewer line
4-4129	1-21-74	416	Replace deteriorated pipe in boiler Rm
4-3881		8158	Structural repair ext.
4-4757	6-17-74	0/E	Repair sewer line
1108	11/17/76	541	Const. of wall
2849	6/10/75	218	install (2) recept.
3477	11/3/74	/	Rpl conduit wire to heater
5234	5/3/76	999	Rpr to boiler
5460	6/23/76	708	Rpl valves.
3376	10/30/76	/	Rpr door
4404	7-19-77	617	Paint 3 classrooms
4482	4-13-78	/	Perform refractory work in boiler #50
1295	6-14-78	640	POC - site dump (Drop training)
4600	4-20-78	380	Paint portions of bldg. 1 coat (see tags)
3344	11-30-79	1731	Install pulley chains on safety vapor
3399	5/30/80	1217	Request & install Repu part on MC bus
2050	1-9-81	613	Clean up oil spill
3610	6-27-80	2008	Rpr overhead crane
3580	2-6-81	660	Repair Water main
4395	2-27-81	409	Make Repair before paint contract

